

LAMP PARTS

FOR

WESTERN ELECTRIC

Petite Constant Potential Enclosed Arc Lamps

TYPES

250, 270, 273, 274, 280, 283, 284, 290, 293, 294

AND

DISCARDED PARTS OF TYPES

260, 270, 271, 280, 281, 282, 290, 291, 292

WESTERN ELECTRIC COMPANY

CHICAGO

NEW YORK

ST. LOUIS

PHILADELPHIA

September 1st, 1901

PETITE ARC

LAMP PARTS

[BLANK PAGE]



CCA

INSTRUCTIONS IN REGARD TO ORDERING

Lamp Parts

PARTS requiring adjustment and fitting, are shown in the cuts assembled ready for insertion into the lamp. Dashpots, Clutches, Negative Plates, Tripods, Shells and Casings should be ordered by catalogue numbers. If individual parts for dashpots or clutches are ordered we cannot guarantee fitting or adjustment. The piece numbers, comprised in an assembled part, appear under the heading of the main number in the list. Unless otherwise specified casings will be furnished in "old copper" finish.

Western Electric Company

CHICAGO
ST. LOUIS

NEW YORK
PHILADELPHIA

LONDON:

Bridge Chambers, 171 Queen Victoria St., E. C.
and North Woolwich, E.

ANTWERP:
32 Rue Boudewyns

PARIS:
46 Avenue de Breteuil

Petite Constant Potential Direct Current Arc Lamps


Types 270, 273, 274, for Burning Singly on 110 Volts
Types 290, 293, 294, for Burning Singly on 220 Volts



Types 270 and 290



Types 274 and 294




Types 273 and 293

Petite Direct Current Constant Potential Arc Lamps


For Burning Two in Series on 220 Volts or Five in Series on 550 Volts



Type 280



Type 284



Type 283

Combined Top, Rheostat & Switch

Types 270 280 290



P-15001



P-15003



P-15007



P-15006

P-15008

	273	274
Types	283	284
	293	294
	250	



P-15020



P-15022



P-15025



26 Porcelain Insulator.




P-15024

P-15008

	270	290
	273	274
Types	283	284
	293	294
	250	280

P-15188



P-15014



20 Porcelain Insulators



P-15016



P-15017



P-15189




P-15018



P-15190 Types 270, 273, 274, 250.



P-15191 Types 280, 283, 284.



P-15193



P-15192 Types 290, 293, 294.

Catalogue of Parts for Petite Arc Lamps


COMBINED TOP, RHEOSTAT AND SWITCH FOR PETITE ARC LAMPS

Piece No.	No. Pieces in Lamp.	Price	Piece No.	No. Pieces in Lamp.	Price
Types 270-280-290					
P15001. Fancy Bell with Insulator and Screw, each	1	\$.34	No. 10x32x1½ flat head iron screw for fastening porcelain insulators, per 100	2	\$1.31
No. P15000. Fancy Bell, each	1	.33	No. 10x32x2½ flat head iron screw for fastening porcelain insulators, per 100	3	2.21
W. E. Special No. 21. Porcelain Insulator, per 100	1	2.07	W. E. Special No. 20. Porcelain Insulators for support of resistance coil, per 100	13	1.38
No. 10x32x1½ flat head iron screw, per 100	1	1.31	Copper Burs F, per 100	16	.22
P15003. Corrugated Top with Screws and Porcelain Insulators each	1	1.09	P15024. Binding Post with Insulation, each	2	.29
No. P15002. Corrugated Top, each	1	.77	No. P15004. Binding Post, each	2	.16
No. 6x32x½ round head brass screw for fastening of rheostat shell, per 100	2	.38	No. 8x32x½ round head brass screw, per 100	4	.59
No. 10x32x½ round head iron screw for fastening top to stem, per 100	1	.48	No. P5204. Micanite Washer 1-16 inch thick, per 100	4	1.95
No. 10x32x1½ flat head iron screw for porcelain insulators, per 100	2	1.31	No. P5632. Asbestos Washer, per 100	4	.15
No. 10x32x2½ flat head iron screw for porcelain insulators, per 100	3	2.21	W. E. Special No. 26. Porcelain Insulator	2	.10
W. E. Special No. 20 Porcelain Insulators for support of resistance coil, per 100	13	1.38	W. E. Special No. 1. Lava Bushing, each	2	.05
Copper Burs F, per 100	16	.22	Copper Bur, F., per 100	4	.22
P15006. Binding Post complete with Insulation, each	2	.27	No. 10x32 Hexagon Brass Nut, per 100	4	.47
No. P15004. Binding Post, each	2	.16	No. P15023. Long Binding Post Stud, each	2	.05
No. 8x32x½ round head brass screw, per 100	4	.59	P15025. Plain Switch Arbor, each	1	.26
No. P5204. Micanite Washers 1-16 inch thick, per 100	4	1.95	P15008. Headless Screw for Arbor, each	1	.05
No. 1. Lava Bushing, each	2	.05	Types 270-273-274-280-283-284 290-293-294-250		
Copper Bur, F., per 100	4	.22	P15189. Contact Wedge and Sleeve	1	.45
No. 10x32 Hexagon Brass Nut, per 100	4	.47	No. P15009. Sleeve, each	1	.19
No. P15005. Short Binding Post Stud, each	2	.05	No. P15010. Contact Wedge, each	1	.14
P15007. Switch Arbor, Ornamental, each	1	.26	No. 6x32x½ round head brass screw, per 100	2	.45
P15008. Headless Screw for Arbor, each	1	.05	W. E. Special No. 14. Lava Bushings, per 100	2	4.30
Types 273-274-283-284 293-294-250			No. P6000. Micanite Washer, 1-16 inch thick, per 100	2	1.20
P15020. Weatherproof Bell with Insulator and Screw, each	1	.49	Copper Bur, C., per 100	2	.07
No. P15019. Weatherproof Bell, each	1	.46	P15014. Switch Jaws Mounted on Bracket, each	1	.49
W. E. Special No. 21. Porcelain Insulator, per 100	1	2.07	No. P15012. Switch Jaw Bracket, each	1	.11
No. 10x32x1½ flat head iron screw, per 100	1	1.31	No. 8x32x½ flat head iron screw, per 100	2	.35
P15022. Weatherproof Top with Screws and Porcelain Insulators, each	1	1.46	No. P5557. Front Blade, each	1	.05
No. P15021. Weatherproof Top, each	1	1.14	No. P5556. Rear Blade, each	1	.05
No. 10x32x½ round head iron screw for fastening top to stem, per 100	1	.48	No. 8x32x½ round head brass screw for connections, per 100	3	.55
			Copper Bur, E., per 100	3	.09
			W. E. Special No. 14. Lava Bushings, per 100	4	4.30
			No. P6000. Micanite Washer, 1-16 inch thick, per 100	4	1.20

Piece No.		No. Pieces in Lamp.	Price
	No. P5555. Washer for Lava		
	Bushing, per 100.....	4	\$.27
	Copper Bur B. for Rivet, per 100	4	.08
	No. P15013. Rivet, per 100....	2	1.52
P15016.	Rheostat Binding Post with Contact Screws, each.....	1	.08
	P15015. Binding Post, each....	1	.07
	No. 8x32x $\frac{1}{4}$ round head brass screw, per 100.....	2	.55
	Copper Bur E., per 100.....	2	.09
P15188.	Insulated Screws for Rheostat Binding Post, each.....	2	.06
	No. 6x32x $\frac{1}{2}$ round head brass screw, per 100.....	2	.45
	W. E. Special. No. 14 Lava Bushings, per 100.....	2	4.30
	No. P5998. Micanite Washers 1-16 inch thick, per 100.....	4	.60
	Copper Bur C., per 100.....	2	.06

Piece No.		No. Pieces in Lamp.	Price
P15017.	Lead Wire (from + binding post to switch), each.....	1	.06
P15018.	Adjusting Wire for Resistance with Connector, each.....	1	\$.05
	No. P5471. Connector, each....	1	.05
	No. 4x36x $\frac{3}{8}$ round head brass screw, per 100.....	1	.35
P15190.	Resistance Coil for Types 270- 273-274, each.....	1	.99
P15191.	Resistance Coil for Types 280- 283-284, each.....	1	1.31
P15192.	Resistance Coil for Types 290- 293-294, each.....	1	.71
P15193.	Inner Globe Ring, each.....	1	.07
	No. P6130. Ring Punching, per 100.....	2	1.78
	No. 4x36x $\frac{1}{2}$ round head brass screw, per 100.....	1	.31
	No. 12 Escutcheon Pins, per 100	1	.12




Marine Lamp, Direct Current, Petite Style



Type 250

Details of Movement

For Types 270 273 274
290 293 294



Details of Movement

For Types 270-273-274-290-293-294

Piece No.	No. Pieces in Lamp.	Price	Piece No.	No. Pieces in Lamp.	Price
P15027. Stem, each	1	\$.27	P15046. Brass Rod for Adjusting Washers, each	1	\$.05
P15028. Upper Part of Yoke, each	1	.21	Copper Bur D., per 100		.14
P15029. Studs for Fastening Lower to Upper Yoke, each	2	.05	No. 6x32 Hexagon Brass Nuts, per 100	2	.80
Copper Bur F., per 100	2	.22	P15047. Shoulder Screws, each	2	.05
No. 8x32 Hexagon Brass Nuts, per 100	2	.99	P15048. Stop Pin for Lever, per 100	1	.83
P15032. Armature and Brass Ring, each	1	.34	P15049. Gas Check Plate, each	1	.88
P15030. Armature Core, each	1	.19	P15050. Bayonets, each	2	.05
P15031. Brass Ring, each	1	.05	No. 6x32x5-16 flat head brass screw for bayonets, per 100	4	.41
No. 2x56x3-16 flat head brass screws, per 100	2	.31	P15178. Insulated Holding-Down Screw for Tripod with Negative Terminal, each	1	.11
P15033. Studs for Armature, each	2	.05	No. 10x32x1½ round head brass screw, per 100	1	1.86
P15034. Nuts for Armature Studs, each	2	.05	No. P5204. Micanite Washer, 1-16 inch thick, per 100	1	1.95
P15035. Adjusting Wire for Regulating Coil, per C	1	1.14	W. E. Special No. 8. Lava Bushing, per 100	1	3.45
No. 6x32x¾ round head brass screws, per 100	1	.41	No. P15051. Negative Terminal, each	1	.05
No. 6x32 Hexagon Brass Nut, per 100	1	.80	No. 8x32x¼ round head brass screw, per 100	1	.55
Copper Bur D., per 100	2	.14	Copper Bur F., per 100	1	.22
P5633. Asbestos Washer for Insulating Switch Ring from Movement, each	1	.05	P15179. Porcelain Insulator Padded with Asbestos, each	2	.05
P15177. Insulated Holding-Down Screws for Switch Ring, each	3	.07	No. P5859. Asbestos Washer, per 100	4	.16
No. 10x32x¼ round head brass screw, per 100	3	1.34	W. E. Special No. 27. Porcelain Insulator, per 100	2	1.29
Copper Bur F., per 100	3	.22	P15180. Insulated Holding-Down Screws for Tripod, each	1	.07
W. E. Special No. 8. Lava Bushing, per 100	3	3.45	No. 10x32x1½ round head brass screw, per 100	1	1.86
No. P5204. Micanite Washer, 1-16 inch thick, per 100	3	1.95	No. P5204. Micanite Washers, 1-16 inch thick, per 100	1	1.95
P5635. Lifting Links for Armature, each	2	.05	Copper Bur F., per 100	1	.22
P15041. Clutch Assembled and Adjusted, each	1	.73	W. E. Special No. 8. Lava Bushings, per 100	1	3.45
No. P5636. Toggle Links, per 100	6	.39	P15057. Lower Carbon Holder, Complete with Thumbscrews and Washers, each	1	.31
No. P15183. Shoulder Rivet for Toggle, per 100	2	.60	No. P15052. Rear Part of Carbon Holder, each	1	.12
No. P15036. Toggle Assembled, each	2	.05	No. P15053. Front Part of Carbon Holder, each	1	.05
No. P15037. German Silver Fulcrum Pins, per 100	2	.72	No. P15054. Shoulder Rivet, each	1	.05
No. P15038. Brass Shoulder Pins, per 100	2	7.34	No. P15055. Thumbscrews for fastening of carbon holder, each	2	.05
No. P15039. Clutch Jaws, each	2	.11	No. P5225. Brass Washers for Thumbscrews, per 100	2	.05
No. P15040. Clutch Base, each	1	.23	No. P15056. Thumbscrew for Carbon Clamp, each	1	.05
No. P15034. Nuts for Brass Pins, per 100	4	.46	P15058. Negative Wire, each		.08
No. 4x36x3-16 round head brass screws, per 100	1	.31			
Copper Bur C., per 100	1	.07			
P15042. Flexible Cord for Clutch, each	1	.06			
P15043. Clutch and Dashpot Lever, each	1	.15			
P15044. German Silver Fulcrum Pin, per 100	1	1.19			
P15045. German Silver Piston Rod Pin, per 100	1	.66			


Piece No.		No. Pieces in Lamp.	Price	Piece No.		No. Pieces in Lamp.	Price
Types 270-273-274							
P15060.	Regulating Coil, each.....	1	\$4.53	No. P5671.	Side Rod with Hole for Clamp, per 100.....	1	\$1.90
	No. P15082. Frame for Regulating Coil, each.....	1	1.43	No. 16.	Escutcheon Pins, per 100.....	14	.05
	No. P5338. Pressboards Washer, per 100.....	4	.47	P15182.	Insulated Screws for Attaching Negative Plate to Tripod, each	2	.08
	No. 6x32x7-16 round head brass screw for attachment of dash-pot, per 100.....	1	.45		No. 10x32x1½ round head brass screw, per 100.....	2	1.86
	No. 6x32 Hexagon Brass Nut, per 100.....	1	.79		W. E. Special No. 8. Lava Bushing, per 100.....	2	3.45
	No. 10x32x½ flat head brass screw for attaching gas check plate, per 100.....	3	.89		No. P5999. Micanite Washer, 1-16 inch thick, per 100.....	2	1.20
	No. 6x32x¼ round head brass screw for fastening of flexible cord, per 100.....	1	.38		No. P15179. Porcelain Insulators Padded with Asbestos, per 100,	2	1.45
	Copper Bur. D., per 100.....	1	.14		Copper Bur F., per 100.....	2	.22
	3¼ lb No. 13 D. C. C. Magnet Wire, each.....		2.65	Types 290-293-294			
P15181.	Insulated Screws for Attachment of Guard Ring, each....	2	.08	P15073.	Lower Yoke, each.....	1	.17
	No. 10x32x½ round head brass screw, per 100.....	2	1.06	P15074.	Regulating Coil, each.....	1	3.97
	Copper Bur. F., per 100.....	2	.21		No. P15082. Frame for Regulating Coil, each.....	1	1.43
	No. P5204. Micanite Washer, 1-16 inch thick, per 100.....	4	1.95		No. P5338. Pressboard Washers, per 100.....	4	.47
	W. E. Special No. 8. Lava Bushings, per 100.....	2	3.45		No. 6x32x7-16 round head brass screw for attachment of dash-pot, per 100.....	1	.45
P15067.	Dashpot Complete with Piston and Piston Rod, each.....	1	.82		No. 6x32 Hexagon Brass Nut, per 100.....	1	.79
	No. P15061. Dashpot Tube, each	1	.14		No. 10x32x½ flat head brass screw for attaching gas check plate, per 100.....	3	1.34
	No. P15062. Dashpot Plug with Flange, each.....	1	.18		No. 6x32x¼ round head brass screw for fastening flexible cord, per 100.....	1	.38
	No. P15083. Tube and Flange Assembled, each.....	1	.33		Copper Bur D., per 100.....	1	.14
	No. P15063. Piston Rod, each..	1	.05	P15075.	Brass Bushings, per 100.....	3	1.39
	No. P15064. Ball Joint, each..	1	.05	P15181.	Insulated Screw for Attachment of Guard Ring, each....	2	.08
	No. P15065. Piston Rod and Ball Joint Assembled, each....	1	.10		No. 10x32x½ round head brass screw, per 100.....	2	1.06
	No. P15066. Piston, each.....	1	.29		Copper Bur F., per 100.....	2	.21
P15069.	Negative Plate with Stem for Cut-Out Wire, each.....	1	.21		No. P5204. Micanite Washer, 1-16 inch thick, per 100.....	4	1.95
	No. P15068. Negative Plate Casting, each.....	1	.16		W. E. Special No. 8 Lava Bushing, per 100.....	2	3.45
	No. P5672. Stem for Cut-Out Wire, per 100.....	1	.85	P15079.	Dashpot Complete with Piston and Piston Rod, each.....	1	.84
	No. P5675. Clamp for Cut-Out Wire, per 100.....	1	.438		No. P15076. Dashpot Tube, each	1	.16
	No. 16. Escutcheon, per 100....	3	.05		No. P15062. Dashpot Plug with Flange, each.....	1	.18
P15072.	Tripod, each.....	1	.55		No. P15084. Tube and Flange Assembled, each.....	1	.38
	No. P15070. Upper Tripod Casting, each.....	1	.20		No. P15077. Piston Rod, each..	1	.05
	No. P15071. Lower Tripod Casting, each.....	1	.20		No. P15064. Ball Joint, each..	1	.05
	No. P5674. Pointer, per 100....	1	.27		No. P15078. Piston Rod and Ball Joint Assembled, each....	1	.10
	No. P5675. Clamp for Cut-Out Wire, per 100.....	1	.438		No. P15116. Piston, each.....	1	.28
	No. P5669. Side Rod with Four Holes, per 100.....	1	1.83		No. P15117. Valve, each.....	1	.05
	No. P5678. Side Rod with Pointer Hole, per 100.....	1	1.05		No. P15118. Valve Stem, each.	1	.05

Piece No.	No. Pieces in Lamp.	Price
P15080. Negative Plate with Stem for Cut-Out Wire , each.....	1	\$.22
No. P15068. Negative Plate Casting, each.....	1	.16
No. P5677. Stem for Cut-Out Wire, per 100.....	1	.82
No. P5675. Clamp for Cut-Out Wire, per 100.....	1	.44
No. 16. Escutcheon Pins, per 100.....	3	.05
P15081. Tripod , each.....	1	.52
No. P15070. Upper Tripod Cast- ing, each.....	1	.20
No. P15071. Lower Tripod Cast- ing, each.....	1	.20
No. P5674. Pointer, per 100....	1	.27
No. P5675. Clamp for Cut-Out Wire, per 100.....	1	.44


Piece No.	No. Pieces in Lamp.	Price
No. P5669. Side Rod with Four Holes, per 100.....	1	\$1.83
No. P5673. Side Rod with Point- er Hole, per 100.....	1	1.57
No. P5678. Side Rod with Hole for Clamp, per 100.....	1	1.05
No. 16. Escutcheon Pins, per 100.....	14	.05
P15182. Insulated Screws for Attaching Negative Plate to Tripod , each	2	.082
No. 10x32x1 $\frac{1}{8}$ round head brass screw, per 100.....	2	1.86
W. E. Special No. 8. Lava Bushing, per 100.....	2	3.45
No. P5999. Micanite Washer, 1-16 inch thick, per 100.....	2	1.20
No. P15179. Porcelain Insulat- ors, per 100.....	2	1.45
Copper Bur F., per 100.....	2	.21

Casing Details


Types 270-290



P-15094




P-15085




P-15103



P-15086



P-15102



P-15098



P-15099




P-15100




P-15088

P-15184

Types 273-293



P-15105



P-15108

Unless otherwise specified casings will be furnished in 'old copper' finish




P-15104




P-15112

P-15185




P-15109




P-15110

P-15186




P-15111


Types 274-294



P-15113




P-15102



P-15114



P-15115



P-15187

P-15114 # P-15115 # P-15187

P-15197

Casing Details

Piece No.	Types 270-290	No. Pieces in Lamp.	Price
P15085.	Switch Ring, each.....	1	\$1.36
P15086.	Guard Ring, each.....	1	.37
P15088.	Rheostat Shell, each.....	1	.74
	No. P5895. Punching for Joint of Shell, per 100.....	1	1.82
	No. 16. Escutcheon Pins, per 100.....	4	.05
P15094.	Movement Shell with Screws, each.....	1	2.94
	No. P15089. Seamless Tube, each.....	1	.60
	No. P15090. Rosettes, each....	2	.06
	No. P15091. Name and patent plate, each.....	1	.05
	No. P15092. Supporting Screws, each.....	2	.05
	No. P15093. Crown, each.....	1	1.44
	No. P15095. Screws for steady-ing reflector, each.....	2	.07
	No. 16. Escutcheon Pins, per 100.....	10	.05
P15184.	Outer Globe Ring with Screws, Hooks and Eyes, each.....	1	1.94
	No. P15096. Globe Supporting Screws, each.....	6	.05
	No. P15097. Globe Ring, each..	1	1.50
	No. P15098. Globe Ring with Supporting Screws, each.....	1	1.68
	No. P15099. Eye, each.....	2	.07
	No. P15100. Supporting Hook, each.....	2	.06
	No. 4x36x $\frac{1}{2}$ flat head brass screw for hook and eye, per 100.....	4	.38
P15102.	Chain with Rings, each.....	2	.05
P15103.	Perforated Ring, (for lamps with glass shade)' each.....	1	.09
	No. 6x32x $\frac{1}{2}$ round head brass screw for attachment of 15103, per 100.....	4	.45


Types 273-293

P15104.	Brass Plate for Stem, each.....	1	.38
P15105.	Guard Ring, each.....	1	.65
P15108.	Movement Shell, each.....	1	1.11
	No. P15106. Seamed Shell, each	1	.79
	No. P15107. Brass Buttons, each	2	.06
	No. P15092. Supporting Screws, each.....	2	.05
	No. P15091. Name and Patent, Plate, each.....	1	.05
	No. 16. Escutcheon Pins, per 100	2	.05

Piece No.		No. Pieces in Lamp.	Price
P15185.	Metal Shade Support and Insulating Ring Assembled, each.....	1	\$2.58
	No. 15109. Outer Ring Supporting Metal Shade, each.....	1	1.23
	No. P15110. Inner Insulating Ring, each.....	1	.67
	No. P15111. Asbestos Strip, each	1	.05
P15112.	Metal Shade, each.....	1	1.00
P15186.	Insulated Screw for 15109 and 15110, each.....	4	.05 $\frac{1}{2}$
	No. 8x32x $\frac{3}{4}$ round head brass screw, per 100.....	4	.86
	No. P5999. Micanite Washer, 1-16 thick, per 100.....	4	1.20
	Copper Bur E., per 100.....	4	.10
	W. E. Special No. 11. Lava Bushing, per 100.....	4	2.58
	No. 6x32x $\frac{1}{2}$ round head brass screw for attachment of metal shade, per 100.....	4	.38
	No. 6x32x3-16 round head brass screw for movement shell, per 100.....	4	.38

Types 274-294

P15104.	Brass Plate for Stem, each.....	1	.38
P15105.	Guard Ring, each.....	1	.65
P15108.	Movement Shell Assembled, each.....	1	1.11
	No. P15106. Seamed Shell, each	1	.79
	No. P15107. Brass Casings, each.....	2	.06
	No. P15092. Supporting Screws, each.....	2	.05
	No. P15091. Name and Patent Plate, each.....	1	.05
	No. 16. Escutcheon Pins, per 100.....	2	.05
P15113.	Ventilating Ring for Movement Shell, each.....	1	1.49
	No. 6x32x3-16 round head brass screw for attachment of ring to movement shell, per 100....	4	.38
P15187.	Outer Globe Ring with Screws, Cams and Cam Levers, each..	1	1.71
	No. P15196. Globe Ring, each..	1	1.02
	No. P15197. Globe Ring with supporting screws, each.....	1	1.06
	No. P15114. Cam, each.....	2	.08
	No. P15115. Camlever, each....	2	.08
	No. 4x36x $\frac{1}{2}$ flat head brass screw for Cam and Lever, per 100...	4	.38
	No. P15096. Globe supporting screws, each.....	6	.05
P15102.	Chain with Rings, each.....	2	.05



Types 271 and 291



Types 260 and 292

Discarded Parts of the following types




"P-15300


270	280	290
271	281	291
260	282	292



"P-15301



"P-15302



"P-15304



P-15306



P-15308




P-15310



P-15311



P-15312




P-15317



P-15321




P-15322



P-15325



Superseded by
"27WE.Co. Special
Porcelain Insulator.



P-15328



Superseded by
"27W.E.Co. Special
Porcelain Insulator.

Discarded Parts of the Following Types:

270	280	290
271	281	291
260	282	292

Part No.	Number in Lamp.	Price	Part No.	Number in Lamp.	Price
P15300. Weatherproof Top for Lamps without Switches, and for types 271, 281, 291, 260, 282, 292, with Snap Switches, each	1	\$.84	P15311. Switch Arbor, each	1	\$.20
P15301. Corrugated Top for Lamps without Switches, and for types 270, 280, 290, with Snap Switches, each	1	.48	P15312. Switch Contact Lever, each	1	.17
P15302. Switch-Ring, drilled and provided with German Silver pins for Snap Switches, for types 280, 281, 282, each	1	1.65	No. P6053. Side Punching with stop, each	1	.05
No. P15303. Switch Ring, each	1	1.12	No. P6052. Side punching without stop, each	1	.05
No. P15331. German Silver Pins, per 100	2	.75	No. P15313. Fibre Bushing, each	1	.05
No. P15119. Brass Stem, each	1	.28	No. P15314. Metal tube for fibre bushing, per 100	1	1.41
P15304. Switch-Ring, drilled and provided with German silver pins for Snap Switches for types 270, 271, 260, each	1	1.20	No. P15315. Crossguide, per 100	1	.46
No. P15305. Switch Ring, each	1	1.12	No. P5102. Copper Bur, per 100	2	1.20
No. P15331. German Silver Pins, per 100	2	.75	No. P5104. Micanite Washer, per 100	2	.10
P15306. Left-Hand Contact of Switch, each	1	.17	No. P15316. Copper Pin, per 100	2	1.03
No. P15307. Casting (left-hand), each	1	.09	P15317. Crank and Arm Riveted Together, each	1	.22
No. P6051. Punching (left-hand), per 100	1	1.75	No. P15318. Crank, each	1	.07
No. 4x36x5-16 Round Head Brass Screw, per 100	2	.34	No. P15319. Arm, each	1	.07
No. 16. Escutcheon Pins, per 100	2	.05	No. P15320. Rivet, per 100	1	.17
P15308. Right-Hand Contact of Switch, each	1	.24	P15321. Actuating Spring, per 100	1	1.14
No. P15309. Casting (right-hand), each	1	.10	P15322. Shell for Type 281, each	1	1.90
No. P6050. Punching (right-hand), per 100	1	1.75	No. P15323. Shell, each	1	1.30
No. 4x36x5-16 Round Head Brass Screw, per 100	2	.34	No. P15091. Name Plate, each	1	.05
No. 16. Escutcheon Pins, per 100	2	.05	No. P15107. Bushings for supporting screws, each	2	.06
P15310. Insulated Holding Down Screw for Switch Contacts, each	4	.06	No. P15092. Supporting screws for shell, each	2	.05
No. 6x32x7-16 Round Head Brass Screw, per 100	4	.45	No. 15324. Brass Studs for fastening of reflector, each	4	.05
No. 14 Lava Bushings, per 100	4	4.29	No. 6x32x $\frac{1}{4}$ Round Head Brass Screw, per 100	4	.38
No. P5999. Micanite Washers, per 100	8	1.20	P15325. Shell for Type 271, each	1	1.85
No. C. Copper Burs, per 100	4	.07	No. P15326. Shell, each	1	1.25
			No. P15091. Name Plate, each	1	.05
			No. P15266. Bushings for supporting screws, per 100	2	1.41
			No. P15327. Supporting screws for shell, per 100	2	2.77
			No. P15324. Brass Studs for fastening of reflector, per 100	4	2.82
			No. 6x32x $\frac{1}{4}$ Round Head Brass Screws, per 100	4	.38
			P15328. Metal Shade with Shell, each	1	1.85
			No. P15329. Metal Shade, each	1	1.20
			No. P15330. Shell, each	1	.57
			No. 16. Escutcheon Pins, per 100	6	.05

